


TRX4MT

Body Assembly


Specifications on this page are subject to change without notice. Every attempt has been made to ensure the accuracy of this drawing; however, Traxxas cannot be held responsible for typographical or other errors.



Chassis Assembly



Specifications on this page are subject to change without notice.
Every attempt has been made to ensure the accuracy of this drawing;
however, Traxxas cannot be held responsible for typographical
or other errors.



REV 240422-R01
See Parts List for a complete
listing of optional accessories.

*See Rear Assembly for transmission exploded view.




Specifications on this page are subject to change without notice. Every attempt has been made to ensure the accuracy of this drawing; however, Traxxas cannot be held responsible for typographical or other errors.



TRAXXAS

9746
2.5x0.45 NL
5158
9746X opt.



9867

9746
2.5x10 BCS
9746X opt.



9764
9764-BLUE opt.
9764-GRAY opt.
9764-GRN opt.
9764-ORNG opt.
9764-RED opt.

9831

9746

2.5x10 BCS

9746X opt.

9746

2.5x16 BCS

9746X opt.

9745

3.5x7x2.5 SLB

9745X opt.

9745

4x8x3 SLB

9745X opt.

9746

2.5x16 BCS

9746X opt.

9745

4x8x3 SLB

9745X opt.

9746

2.5x16 BCS

9746X opt.

9745

1.6x12 BCS

(self-tapping)

9746X opt.

9745

4x8x3 SLB

9745X opt.

9746

2.5x14 BCS

9746X opt.

9745

1.6x7 BCS (self-tapping)

9746X opt.

9745

9855

9746

2.5x14 BCS

9746X opt.

9745

1.6x7 BCS (self-tapping)

9746X opt.

9745

9855

9746

2.5x14 BCS

9746X opt.

9745

1.6x7 BCS (self-tapping)

9746X opt.

9745

9855

9746


2.5x14 BCS

9746X opt.

9745

1.6x7 BCS (self-tapping)

9746X opt.




Transmission Assembly

Available fully assembled as part #9791;
part #9791R opt., 9791X opt.

TRX4MT

Rear Assembly



9867

9746
2.5x0.45 NL
5158
9746X opt.

REV 240422-R01

See Parts List for a complete
listing of optional accessories.

Specifications on this page are subject to change without notice. Every
attempt has been made to ensure the accuracy of this drawing; however,
Traxxas cannot be held responsible for typographical or other errors.